Machine Update

NSLS-II Town Meeting

Emil Zitvogel

Wednesday August 5, 2015






Topics

- Statistics
- Schedule
- Storage Ring Performance
- Booster Dipole Power Supply Failure
- Spring Shutdown Highlights
- Aug-Sep Shutdown Plans
- Closing Remarks





Statistics Through July31st



Operations: 1740.4 hrs
Injection/Setup: 59.1 hrs
Sched. Studies: 851.7 hrs
Sched. Maintenance: 194.2 hrs
Failure: 400.3 hrs
Shutdown: 859.6 hrs
Unscheduled Operations: 24.7 hrs

Reliability:

Of 2074.4 scheduled hrs from Feb-July 2015:

Operations: 83.9%

Injection/Setup: 2.8%

Failure: 13.3%

Availability:


Of 2074.4 scheduled hrs from Feb-July 2015:


Delivered Beam Time: 85.1%






Statistics Through July 31st





Schedule







Schedule

		S	eptem	ber				
Day	The second secon							
	0-4	4-8	8-12	12-16	16-20	20-24		
1	D	D	D	D	D	D		
2	D	D	D	D	D	D		
3	D	D	D	D	D	D		
4	D	D	D	D	D	D		
5	D	D	D	D.	D	D		
6	D	D	D	D	D	D		
7	D	D	D	D	D	D		
8	D	D	D	D	D	D		
9	D	D	D	D	D	D		
10	D	D	D	D	D	D		
11	D	D	D	D	D	D		
12	D	D	D	D	D	D		
13	D.	D	D	D.	D	D		
14	D	D	D	D	D.	D		
15	D	D	D	D	D	D		
16	D	D	D	D	D	D		
17	D	D	D	D	D	D		
18	D	D	D	D	D	D		
19	D	D	D	D	D	D		
20	D	D	D	D	D	D		
21	D	D	D	D	D	D		
22	D	D	D	D	D	D		
23	D	D	D	D	D	D		
24	D	D	D	D	D	D		
25	D	D	D	D	D	D		
26	D	D	D	D	D	D		
27	D	D	D	D	D	D		
28	D	D	S	S	S	S		
29	S	S	S	S	S	S		
30	S	S	S	S	S	S		

Half Shifts							
0-4	4-8	8-12	12-16	16-20	20-24		
S	S	S	S	S	S		
S	S	S	S	S	S		
S	S	5	S	S	5		
S	S	S	S	S	S		
S	S	S	S	S	S		
S	S/M	M	M	M/S	S		
S	S	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	O/M	M	М	M/S	S		
S	S	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	S	S	S		
S	S	S	S	S	S		
S	5	S	5	S	S		
S	S/M	M	M	M/S	S		
S	S	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	O/M	M	M		S		
S	S	0	0	0	0		
0	0	0	0	0	0		
0	0	0	0	0	0		
0	0	0	S	5	S		
	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S	0-4	0-4	0-4		

October

Day	November Half Shifts						
1	0-4	4-8	8-12	12-16	16-20	20-24	
1	S	S	S	S	S	S	
2	S	S	S	S	S	S	
3	S	S/M	М	M	M/S	S	
4	S	S	0	0	0	0	
5	0	0	0	0	0	0	
6	0	0	0	0	0	0	
7	0	0	0	0	0	0	
8	0	0	0	0	0	0	
9	0	0	0	0	0	0	
10	0	O/M	M	M	M/S	S	
11	S	S	0	0	0	0	
12	0	0	0	0	0	0	
13	0	0	0	0	0	0	
14	0	0	0	S	S	S	
15	5	S	S	S	S	S	
16	S	S	S	S	S	S	
17	S	S/M	M	M	M/S	S	
18	S	S	0	0	0	0	
19	0	0	0	0	0	0	
20	0	0	0	0	0	0	
21	0	0	0	0	0	0	
22	0	0	0	0	0	0	
23	0	0	0	0	0	0	
24	0	0	S	S	S	S	
25	S	S	S	S	D	D	
26	D	D	D	D	D	D	
27	D	D	D	D	D	D	
28	D	D	D	D	D	D	
29	D	D	D	D	D	D	
30	D	D	D	D	D	D	

December									
Day	Half Shifts								
	0-4	4-8	8-12	12-16	16-20	20-24			
1	D	D	D	D	D	D			
2	D	0	D	D	D	D			
3	D	D	D	D	٥	D			
4	D	0	D	D	D	D			
5	D	D	D	D	D	D			
6	D	D	D	D	D	D			
7	D	D	D	D	D	D			
8	D	D	D	D	D	D			
9	D	D	D	D	D	D			
10	D	0	D	D	D	D			
11	D	0	D	D	D	D			
12	D	D	D	D	D	D			
13	D	D	D	D	D	D			
14	D	D	D	D	D	D			
15	D	D	D	D	Đ	D			
16	D	D	D	D	D	D			
17	D	D	D	D	D	D			
18	D	0	D	D	D	D			
19	D	D	D	D	D	D			
20	D	0	D	D	D	D			
21	D	D	D	D	D	D			
22	D	D	D	D	D	D			
23	D	D	D	D	D	D			
24	D	D	D	D	D	D			
25	D	0	D	D	D	D			
26	D	D	D	D	D	D			
27	D	D	D	D	D	D			
28	D	D	D	D	D	D			
29	D	D	D	D	D	D			
30	D	D	D	D	D	D			
31	D	D	D	D	D	D			
Total Hours - December 744									

Total Hours - September Total Days - September

720

Total Days - October

31


Total Days - November


Total Hours - December Total Days - December

BKUUKHMVEN



Storage Ring Performance






300 mA!

Routine Ops at 150 mA





Storage Ring Performance



Preparation for Top-Off operation continues at a good pace.

- ✓ 20% bunch-to-bunch variation has been achieved (ignoring the leading and trailing bunches)
- ✓ 0.5% variation in ring current has also been achieved.

The Top-Off Safety System fabrication and installation is continues on schedule.

Results from Top-Off Injection Studies on July 28th






- At 1:31 am on July 12th the Operator on-duty received an alarm that the BD1 power supply had tripped off.
- The booster dipoles are fed in 2 strings with 2 separate but identical power supplies, BD1 and BD2.
- The power supply ratings are 750 A and 700 V which is required to drive the magnets to full field @ 3GeV in only 300 ms. The supplies were manufactured by Danfysik
- After attempts to reset the supply via the control system an operator and floor coordinator inspected the supply and found that both the DC output breaker and the AC line breaker had opened.
- Calls went out to technical experts.
- Upon their arrival on Sunday morning, they found that the supply had extensive damage from internal arcing.
- This was obviously going to require some time to complete the repair.



Driver Cards



Damaged IGBTs and Their Driver Cards in the BD1 Power Supply

IGBT stands for Insulated Gate Bipolar Transistor

IGBTs Mounted Behind Cooling Plate





- The root cause is believed to be a damaged high voltage cable in the power supply.
- Repairs were completed late on Monday. After careful inspection and testing in an inactive state the power supply was re-energized.
- At this point the supply failed again in the same manner.
- Following additional failures we obtained an AC transformer that allowed us to perform tests at current-limited, intermediate voltages giving us insight and control of the method of failure.
- We were also fortunate to redirect the Danfysik engineer who designed and built the power supply from his vacation in Canada.
- It was discovered that the specifications for our spare IGBTs differed from the original IGBTs but had the same part number. The gate drive resistance needed to be 4 ohms for the spare components instead of 2 ohms required and built into the supply for the original components.





BD1 IGBT Failures

An Original IGBT

A Replacement IGBT





- Following complete replacement of all IGBTs with an upgraded part, the power supply was able to be returned to full service on July 24th at 3:05 pm.
- Our thanks go out to everyone involved with the repair for the long and frustrating hours spent chasing this problem.
- Despite the high power that they were working with, all activities were conducted with safety having the utmost importance.





Spring Shutdown Highlights

- Installed three ABBIX IVUs in cells 16 & 17 (AMX/FMX & LIX)
- Finished installation of ABBIX front ends
- Baked & final surveyed IVU straights & front ends
- Began testing IVU controls In-situ
- Cable pulling and floor prep work for NEXT front ends
- Modified ratchet wall for Partner (XFP) beamline
- Installed compound refractive lens in IXS front end
- Installation work for Top-off injection
- Preparation work for future second RF cavity
- PPS re-certification of linac, booster, SR, & 3 beamlines





Spring Shutdown Highlights





LIX IVU in Cell 16



AMX/FMX IVUs in Cell 17

Provided by Greg Fries



AMX/FMX Front End in Cell 17



Aug-Sep Shutdown Plans

- Install NEXT IVU in cell 4 (ISR)
- Finish installation of NEXT ISR & ISS front ends
- Installation work on balance of NEXT front ends
- Cable pulling & floor prep work on Partner & BDN front ends
- May install second RF cavity, not yet determined
- Repair broken pole tip on IXS IVU
- Finish Top-off injection installation, testing & installation
- PPS certification of ABBIX LIX beamline
- PPS re-certification of 3 beamlines





Closing Remarks

Except for the booster dipole failure, NSLS-II has performed very reliably and with the performance that we expect at this early stage

We expect that Top-Off operation will commence on schedule early in FY16

We are pleased to welcome and support our first users

Installation of new beamline components continues at a quick pace

Thank you



